

Lard Oil Company, Inc. Oil Spill

Photo Log

Description: Oil stain in grass leading away from the Lard Oil facility

Category: Site Photo

Latitude:

Date Taken: 8/18/2016

Longitude:

Tags:



Description: Oil stain on a house.

Category: Site Photo

Latitude:

Date Taken: 8/18/2016

Longitude:

Tags:



Description: Oil in a ditch one block from the Lard Oil facility.

Category: Site Photo

Latitude:

Date Taken: 8/18/2016

Longitude:

Tags:



Description: Emulsified oil on the ground below damaged fence of Lard Oil facility

Category: Site Photo

Latitude:

Date Taken: 8/18/2016

Longitude:

Tags:



Description: 5-gallon oil containers that were washed into a yard.

Category: Site Photo

Latitude:

Date Taken: 8/18/2016

Longitude:

Tags:



Lard Oil Company, Inc. Oil Spill

Photo Log

Description: Emulsified oil on the carport of a residence.

Category: Site Photo

Latitude:

Date Taken: 8/18/2016

Longitude:

Tags:



Description: Fenceline of the Lard Oil facility. Floodwaters damaged the fence and carried some containers off site.

Category: Site Photo

Latitude:

Date Taken: 8/19/2016

Longitude:

Tags:

